

AD-A099 247

CORPS OF ENGINEERS WALTHAM MA NEW ENGLAND DIV
ENVIRONMENTAL ASSESSMENT, NORTH NASHUA RIVER CHANNEL IMPROVEMENT--ETC(U)
NOV 77

F/6 13/2

NL

UNCLASSIFIED

1 OF 1
40 A
039447

END
DATE
REMOVED
6-8-81
DTIC

AD A 099247

DTIC ACCESSION NUMBER

LEVEL

Corps of Engineers, Waltham, MA INVENTORY
New England Div

NORTH NASHUA River Channel Improvement
FITCHBURG LOCAL PROTECTION, Fitchburg, Massachusetts

DOCUMENT IDENTIFICATION

Nov. 77


DISTRIBUTION STATEMENT A

Approved for public release
Distribution Unlimited

DISTRIBUTION STATEMENT

ACCESSION FOR		 <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
NTIS	GRA&I	
DTIC	TAB	
UNANNOUNCED		
JUSTIFICATION		
BY		
DISTRIBUTION / <u>Per Ltr. on file</u>		
AVAILABILITY CODES		
DIST	AVAIL AND/OR SPECIAL	
<u>A</u>		

DISTRIBUTION STAMP



DATE ACCESSIONED

DATE RECEIVED IN DTIC

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDA-2

AD A 099 247

ENVIRONMENTAL ASSESSMENT

NORTH NASHUA RIVER CHANNEL IMPROVEMENT

FITCHBURG LOCAL PROTECTION FITCHBURG, MASSACHUSETTS

DISTRIBUTION STATEMENT A

Approved for public release
Distribution Unlimited



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS.

NOVEMBER 1977

03 27 026

ENVIRONMENTAL ASSESSMENT

NORTH NASHUA RIVER CHANNEL IMPROVEMENT
FITCHBURG LOCAL PROTECTION
FITCHBURG, MASSACHUSETTS

Prepared by

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASSACHUSETTS 02154

November 1977

DISTRIBUTION STATEMENT A

Approved for public release
Distribution Unlimited

Environmental Assessment

North Nashua River Channel Rehabilitation
Fitchburg Local Protection
Fitchburg, Massachusetts

Table of Contents

<u>Paragraph No.</u>	<u>Title</u>
1.	Project Description and Location
2.	Environmental Setting Without The Project
3.	The Environmental Impact of the Proposed Action (1) Bank Restabilization (2) Rock and Debris Removal (3) Granite, Concrete and Gabion Wall Construction (4) Concrete Cribbing and Grouted Riprap Repair (5) Selective Streambank Vegetation Removal
4.	Any Adverse Environmental Effects Which Cannot be Avoided Should the Proposal Be Implemented
5.	Alternatives
6.	The Relationship Between Local Short Term Uses of Man's Environment and the Maintenance and Enhancement of Long-Term Productivity
7.	Identification of "Any Irreversible or Irretrievable Commitment of Resources Which Would Be Involved in the Proposed Action Should it be Implemented"
8.	Environmental Factors a. Aesthetic b. Fisheries c. Wildlife Habitat d. Plant Life e. Recreation f. Noise g. Historical h. Water Quality
9.	Economic and Social Impacts

10. Summary
11. Coordination with Other Agencies
12. Conclusions

Plates

1. Channel Rehabilitation - General Plan No. 1
2. Channel Rehabilitation - General Plan No. 2
3. Channel Rehabilitation - General Plan No. 3
4. Channel Rehabilitation - General Plan No. 4

Attachments

1. Abridged Scope of Work

1.00 PROJECT DESCRIPTION

This project proposes the rehabilitation of the North Nashua River Local Protection Project. It consists of repair and/or reconstruction of those walls, cribs, and grouted riprap which have deteriorated. In addition, there will be removal of channel obstructions and depositions and reshaping and scraping the bottom so as to provide a relative smooth channel with relative uniform width at various places in the channel, large isolated stones will be placed randomly for environmental enhancement.

Because of high channel velocities during flood periods, banks are required to be protected against erosion, and consequent deposition in the improved channel. Within the past 40 years, there has been some major flooding in the North Nashua River Basin. Four substantial floods have occurred between the years 1936-1955. In 1937, work was done under a Work Relief Project to improve conditions in the river and provide a means of flood control. It consisted mainly of installation of cribs and walls, and also placement of grouted riprap. Since then only emergency repair work has been done, once in 1955, and again in 1968. This work consisted of removal of gravel deposits and debris, and filling washed-out riverbanks. Concrete cribbing was also stabilized.


Over the years, these works have deteriorated so extensively that they no longer fulfill their design function. The cribbing

is broken, or covered by stone or plant growth. Concrete slabs have fallen into the river, adding to the already existing debris. The bottom of the river is covered mostly by sludge from the paper mills, with the water carrying paper fibers, creating stagnant pools of the sludge.

The intent of the project is to restore the deteriorated channel to its 1937 condition and capacity of 9,000 cubic feet per second. It is expected that the rehabilitation work will improve the visual aspects of the channel and riverbanks, while also providing a harmonious relationship with the stream environment and its functional purpose of flood control.

The existing project area begins upstream in the city of Fitchburg at the site of the now removed Cowee's Mill Dam, and extends 5.5 miles downstream to the Leominster town line below the Fitchburg Airport. The immediate area of interest extends from Cowee's Mill Dam 4 miles downstream to the vicinity upstream of the Falulah Road Bridge. An abridged scope of the work is shown on Attachment No. 1.

FITCHBURG



CONCRETE RETAINING
WALL CONSTRUCTION

RIPRAP
RESTORATION

RIPRAP
RESTORATION

CONCRETE CRIB
CHANNEL CLEANING

CONCRETE
RETAINING WALL
CONSTRUCTION

RIPRAP
RESTORATION

ROLLSTONE HILL

CHANNEL IMPROVEMENT

MERRIMACK RIVER FLOOD CONTROL PROJECT
NORTH NASHUA RIVER BASIN


CHANNEL IMPROVEMENT
AND RESTORATION

FITCHBURG, MASSACHUSETTS
SEPTEMBER 1977
DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION CORPS OF ENGINEERS
WALTHAM, MASS.

NOTE :
SEE NED DRAWINGS MER-34 PLATES I-4
FOR DETAILS OF WORK AND SPECIFIC LOCATIONS.

LOCATION PLAN

SCALE : 1:6,000
Sov. 0 500



2.00 ENVIRONMENTAL SETTING WITHOUT THE PROJECT

The North Nashua River Basin is situated in north-central Massachusetts in the northern portion of Worcester County and north-west Middlesex County. The study area, located in Fitchburg, is one of the 10 Standard Metropolitan Statistical Areas (SMSA) in Massachusetts and constitutes the major population center within the basin. The river, above the confluence of Baker Brook, controls some 64 square miles of watershed drainage.

The North Nashua River is formed at the confluence of the Whitman River with Flagg Brook in the city of Fitchburg, Worcester County, Massachusetts at an elevation of 590 feet above mean sea level. The principal tributaries are Whitman River, Flagg, Phillips, Baker and Monoosnoc Brooks, with a number of smaller streams adding to the system.

The river flows in a substantially west to east direction through a typically urban industrially and commercially oriented portion of the city. The surrounding topography is characterized by wide valleys and broad, steep-sided hills, affording a watershed which is highly conducive to rapid run-off.

The existing protective works at Fitchburg were constructed following the major flood of 1936. At several places earth banks were protected with concrete crib walls, at other locations the riverbed and toes of the banks were protected against scour by

grouted riprap. The work included channel enlargement, relocation of the outlet of Punch Brook, and removal of several abandoned dams.

Upon examination of the existing project, it was found that its present condition has vastly deteriorated. Cultural debris in the river includes discarded shopping carts, trash, and paper fibers; there is also a large amount of rock debris. Large stone slabs which were either remains of old structures, or of unknown origin have tumbled into the stream along the bank.

At a number of sites, observations included deteriorated concrete cribbing, some with dumped granite in front of it. The banks at River Street Bridge, Circle Street Bridge, and Walnut Street were among those which were in the worst condition.

At certain areas around the banks a large amount of repair was needed. They have either eroded to the point of needed repair, or had rock landslides.

The basin is a center of industrial and commercial areas critical to the economy of central Massachusetts. Manufacturing is the principal occupation, and employment by industries within the floodplain of the river represents over 50% of the total employment in Fitchburg. The serious consequences of any additional flooding of past magnitudes would gravely retard the current progress of economic and social well being.

The stream flow is moderately rapid because of the moderately steep gradient of the streambed.

Although pollution is still quite evident in the present state of the river, steps are being taken to improve the river's condition. Construction and operation of two wastewater treatment plants have improved the condition considerably over the past couple of years.

The primary cause of pollution was the discharge of industrial wastes, principally paper wastes, along the upper and middle portions of the river. Measures are being taken by the paper companies and other industries to diminish the discharge of wastes directly into the river. Although evidence of wastes are still apparent in the river, its condition is an improvement over what it has been in the past. With the diminution of discharge wastes, the North Nashua will improve in the future with its moderate flow and self-scouring action.

The natural setting surrounding the North Nashua is typical of a stressed, urbanized environment. Aquatic fauna have been reduced as a result of past pollution and accumulated paper wastes.

Many of the tall trees along the top of the banks have been in existence for at least 40 years, as seen from historical photographs. Oaks, maples, willows and poplars are among those present. Shrubs and overgrowth immediately along the river are pollution - tolerant species.

Because of the years of pollution, the North Nashua River is not used for any recreational purposes. A Greenway belt along a section of the river has been proposed in order to provide recreational opportunities

for the people of Fitchburg along the banks of the river. Bicycle and jogging paths and walkways have been proposed. Development plans are being actively pursued by local interests.

3.00 THE ENVIRONMENTAL IMPACT OF THE PROPOSED ACTION

Major actions that will be undertaken are:

- (1) Bank Restabilization
- (2) Rock and Debris Removal
- (3) Granite, Concrete and Gabion Wall Construction
- (4) Concrete Cribbing and Grouted Riprap Repair
- (5) Selective Streambank Vegetation Removal

(1) Bank Restabilization

Bank restabilization will be implemented at the site of the now removed Cowee's Mill Dam, and also in the vicinity of the Fallulah Street Bridge. This work will consist of placing large stones, slabs and dumped rock upon the sides of the banks. Construction activities will necessitate the cutting and grading of the existing areas. These areas will be stabilized and revegetated in order to mitigate any undesirable affects.

Work will also consist of the removal of debris which has collected at the foot of the banks. This will aid in keeping an unimpeded flow. This action will also necessitate the reshaping of the banks at the specific areas where debris removal will be implemented.

No adverse effects on the environment can be foreseen.

(2) Rock and Debris Removal

Removal of rock and debris will have a tendency to improve the appearance of the river. The intent of this work is to restore the natural river bed and eliminate areas of sluggishness within the stream.

As a result of this work, some sediment will be released, but only for a short-term and will most likely settle back. Fiber waste which has accumulated over the years will be flushed out with any high river flows. These accumulated wastes should not continue to build up as the introduction of new fiber diminishes. There will be no adverse effects on any aquatic species due to their reduction from past pollution.

(3) Granite, Concrete and Gabion Wall Construction

Wall construction will be undertaken at the following sites which can be located on the various plates.

Concrete - Location F, O, P and Q

Granite - Location B

Gabion - Location A

The impacts as a result of this construction will be minimal. In cases where it necessitates the removal of vegetation, revegetation measures will be implemented.

(4) Concrete Cribbing and Grouted Riprap Repair

This repair work will have little adverse effect on the surrounding environment. Upstream of Oak Hill Road some Japanese bamboo is abundant in front of the walls which require repair. Although this will be removed, it is a minor effect, as natural vegetation will most likely occur.

(5) Streampbank Vegetation Removal

Channel rehabilitation will require the removal of some trees on the river banks. Tree removal will be kept to a minimum and will occur only in those areas where there may be interference with flood flows. Selective removal of vegetation will be conducted as outlined in the Scope of Work (Attachment No. 1).

Clearing in the channel area in zone 1 (0-8) will insure the integrity of the flood control channel and serve to maintain the desired hydraulic character of the channel. The aesthetic impacts of this clearing will be minimal as small shoots and other shrub foliage will be retained.

Clearing in zone 2 will further maintain the integrity of the project while mitigating any potential loss of aesthetics. New trees from nursery stock will be planted along the top of channel banks in areas where trees are taken out.

Trees would be selectively marked for clearing by members of the Corps' Environmental Analysis Branch in coordination with the city of Fitchburg. Designated new planting will also be coordinated.

All lands disturbed by the rehabilitation work will be replanted with grass. Trees and shrubs will also be replanted in certain areas of publicly owned land where flood flow will not be impeded. While tree planting possibilities are limited by the narrow shape of the channel in most of the project area, planting of select shrubs will be possible in many areas. Final revegetation measures will take into consideration local plans for development of a recreation greenbelt along the river.

4.00 ANY ADVERSE ENVIRONMENTAL EFFECTS WHICH CANNOT BE AVOIDED
SHOULD THE PROPOSAL BE IMPLEMENTED

Any adverse environmental effects which can be considered would be those associated with the removal of large trees along the banks of the river. Removal will be carried out only in those areas where the trees, if fallen into the river, would impede flow or create a hazard during flooding conditions. Shrubs and overgrowth along the immediate bank of the river will be removed by construction activities and/or for flood control purposes. Mitigation procedures will be carried out to eliminate any landscape scars as a result of construction and the movement of heavy equipment.

5.00 ALTERNATIVES

The local protection works in the city of Fitchburg were only one of the many projects deemed necessary to alleviate the total flooding problem. All practicable means of solving the flood control problem study area were considered. Inasmuch as the project is a rehabilitation of existing local flood protection facilities no other structural alternatives were considered.

The possibility of nonstructural measures was investigated and an analysis of nonstructural types of alternatives is as follows:

<u>Alternative No.</u>	<u>Plan</u>	<u>Comment</u>
1	No Action	The "no action" plan would be to leave the existing project in its present condition of disrepair and with physical obstructions to river flow. There would not be any monetary costs involved, however, and such a course of action would be unsuitable and not be an aid in reducing flood problems.
2	Evacuation of Floodplain	The removal of all existing development in the floodplains of the Fitchburg area would cause tremendous disruption of human needs and resources. It would cause adverse social and institutional effects associated with large scale relocation and the cost, although not estimated, would be exorbitant. Such a plan would eliminate the need for channel improvements.
3	Floodplain Management	This plan would greatly reduce further encroachment of floodplain areas, however, it does not protect the highly developed areas of Fitchburg against floods. The floodplain in the city is predominantly commercial and industrial with large content values (i.e., raw materials, equipment and manufactured goods).

4	Floodproofing and Evacuation	This alternative provides individual type flood protection for some properties and areas. However, areas and bridges, roads, etc., between the protected buildings would remain subject to flooding, siltation and debris deposition. It does have potential application for some individual properties but not for flooded areas as a whole.
5	Removal of All Existing Works	The possibility of removing all the existing works and starting all over would be impractical. Also it would not significantly increase protection over that provided by the proposed project.
6	Channel Rehabilitation	This alternative involves the accomplishment of physical improvements to an existing accepted project. There will be minimum environmental, social-economic impacts and disruption to existing private and public facilities, enterprises, etc. The Improvement Costs are not excessive and the Benefit-Cost Ratio of the project is favorable and above unity and will provide a reduction in losses from flooding.

Due to the congested built-up area of the city floodplain which mainly comprises a commercial and industrial development, it is considered that the possible nonstructural alternatives are not totally feasible, acceptable or suitable.

The channel rehabilitation project is considered the most acceptable alternative from the points stated above. The channel rehabilitation project has been the authorized project since 1966 and is the "selected" plan of prior studies and consideration of other type alternatives. An updated review of the project has been made and it is considered that the channel rehabilitation remains sound and should be accomplished.

6.00 THE RELATIONSHIP BETWEEN LOCAL SHORT-TERM USES OF MAN'S ENVIRONMENT
AND THE MAINTENANCE AND ENHANCEMENT OF LONG-TERM PRODUCTIVITY

The rehabilitation project will enhance the appearance of the area and will result in a stability of flood control works.

The area surrounding this section of the North Nashua River has been industrialized since the mid 1700's. The original restoration works were built in 1937 to insure the city of Fitchburg protection against flood damage.

The rehabilitation of the flood control works is to insure and promote the continued use of the industrialized area by man. The project will also enhance any long-term productivity of natural vegetation along the banks of the river provided that it is maintained in the future.

There will be no new commitment of natural resources.

7.00 IDENTIFICATION OF "ANY IRREVERSIBLE OR IRRETRIEVABLE COMMITMENT OF RESOURCES WHICH WOULD BE INVOLVED IN THE PROPOSED ACTION SHOULD IT BE IMPLEMENTED"

There will be no irreversible or irretrievable commitment of resources which would be involved in the proposed local protection project should it be implemented, other than the labor and material required to construct the project.

Also committed would be approximately \$2 million needed to complete the rehabilitation project.

8.00 ENVIRONMENTAL FACTORS

The factors listed have been observed and reviewed as to the kinds of effects they will have in the construction area.

The various environmental impacts associated with this project have been categorized under the following principal headings: Aesthetics, Fisheries, Wildlife Habitat, Plant Life, Social, Noise and Historical.

Because each area of the river looked at was in poor condition, the environmental factors listed will have a minimal impact.

a. Aesthetic - The appearance of the local protection project will be improved by completion of the project. Improvement will result from the removal of debris, repair of deteriorated works and aesthetic enhancement measures such as texturing of concrete walls and replanting of riverbanks.

b. Fisheries - The survey did not reveal any forms of fish life; therefore, there will be no impact on fisheries. All species have long since been destroyed.

c. Wildlife Habitat - The area is not a significant wildlife habitat; therefore, there will be no impact.

d. Plant Life - Certain shrubs and trees which may interfere with floodwater flow will be removed during construction. Measures will be taken to mitigate vegetation losses when possible by replanting selected shrubs and small trees at higher elevations above the riverbed.

e. Recreation - At present the river is not used for any recreational purposes, and the commercial usage will not be affected. This flood control project will help to insure social and economic well-being. The new rehabilitation work will improve the visual aspects of the channel and the riverbanks. All work is being coordinated with the city of Fitchburg to assist in their plans for future recreational development along the river.

f. Noise - Noise will increase, but only during construction

9.00 ECONOMIC AND SOCIAL IMPACTS

Planning for flood control requires an understanding of the many diverse forces interacting in the proposed impact (study) area. Moving towards economic growth, housing and industrial development, protection of valuable natural resources, higher or lower taxation, changes in transportation patterns, etc. will affect the quality of life in any particular region. Complex interacting social, economic, and environmental factors may bring about both adverse and beneficial effects to the same community.

Having as much information, and raising as many questions and issues as possible is essential in order to better examine different alternatives and arrive at those plans which meet most consensus and which may be most practical and desirable. Such plans would capitalize on beneficial effects while minimizing or mitigating possible adverse effects in both the short and long run.

Fitchburg has a well balanced economic base and accounts for one-half of the firms in the SMSA, 55% of the annual payroll, and 53% of the average annual employment. Manufacturing with 52% of the total employed population accounts for the largest source of employment. The three leading firms, measured in employment, in order of importance were fabricated metals, paper products, and machinery industries (except electrical). Within the watershed area and principally in Fitchburg, paper production amounts to 20% of the total in Massachusetts. In

the past ten years, the population in Fitchburg has remained relatively stable; yet the SMSA's population has increased by 8%. Thus the city of Fitchburg is the employment center for the population of approximately 100,000 residing in the SMSA.

In the past, employment has been hampered by the attraction of many of the region's industries to other parts of the nation. High wages, ever increasing tax burdens, and the high cost of energy and transportation have led to the exodus of manufacturing firms from both the region and state. The unemployment rate during 1976 was 10-1/2% for the SMSA. This was 3% higher than the national average. Therefore, anything that can contribute to the development of employment opportunities in the region should be welcomed.

The positive contribution of the project is the prevention of flood losses. Physical losses include only such losses or damage to structures, machinery and stock, and cost of clean-up and repairs. Non-physical losses include loss of unrecoverable wages and business cost of temporary facilities, and increased cost of operation.

Other positive effects can be associated with the proposed or examined projects. These could include: avoidance of road washouts thus aiding the motorists and travelers, possible additional recreation, reduction of the probability of injury or death attributed to flooding, the easing of the fear of flooding, the reduction of the possibility of flood waters disrupting water supply and sewage

collection systems which may cause contamination and spread of disease, the availability of jobs and employment opportunity during construction of projects and help in the maintenance of employment.

Such flood protection would result in economic and social enhancement of Fitchburg in particular and the watershed region in general, in the long run. The reduction of damages from floods would yield great economic benefits, especially to industry and may halt the flight of manufacturing jobs. It may reduce the abnormally high level of unemployment and at the same time encourage industrial growth. The serious consequences of any additional flooding of past magnitudes would gravely retard the current progress of economic improvement and social well-being.

All of the project plans would cause some local air and noise impacts because of clearing, grading and filling operations during the 1-1/2 year construction period. All local streets would experience increased traffic from trucks bringing in materials for construction and removing debris. Such truck traffic would bring corresponding air quality, noise, safety, and congestion impacts. Most effects during any project construction tend to be temporary, rather intense and impact more limited to the specific site location. These impacts are of a temporary nature and should cause only minor inconvenience. Impacts after project implementation may be according to plans as well as unforeseen. Some will be site specific; others will go beyond the locality.

The non-action alternative shifts the major responsibility and burden of flood protection to those who live and work on the flood plain. Under the no action (do nothing) alternative, no new regional or local structural projects are built as a possible solution to reduce flood damages. No action means forfeiting potential benefits such as construction related jobs, reduced fear from flooding and the long-run security of decreased flood damages.

10.00 SUMMARY

Based on review of relevant facts pertaining to the public need and environmental considerations, the conclusion reached is that the rehabilitation of the local protection project is in the best public interest. The following points were considered pertinent in evaluation of the project:

(1) The environmental impacts of the project are considered to be very minor. As stated previously, pollution by paper waste and sewage has eliminated any aquatic species which may have inhabited this area of the river. Therefore, any repair work alone will not displace fish or any other aquatic animal species.

Aquatic life which may be found downstream from the project area may have short-term stress as a result of disturbed sediment being carried downstream. Associated turbidity will be reduced to ambient prevailing conditions several hundred feet downstream of work areas. (This effect will be minor and temporary.)

(2) Social well-being must be considered. In allowing the present conditions to remain, the surrounding areas would continue to be exposed to flood damage as in the past. Potential damage due to flooding would most likely increase in the future.

(3) The economy of the city would be greatly affected by any flood damage which may occur. Many economic hardships would result as a consequence of flooding. In addition to the damage to private property, a flood would cause damage to Fitchburg's industries, the city's main source

of income. Temporary or even permanent shutdown of plants would result.

The proposed maintenance project has been found to be the only practicable cause of action. Environmental effects have been considered and found to be minimal and total public interest has been considered. The conclusion is that, with all the considerations and alternatives examined, the repair project should proceed.

It is opinioned that an Environmental Assessment in lieu of an Environment Impact Statement (EIS) is applicable and sufficient for assessing and evaluating the impacts caused by the project for the following reasons:

- a. The work involves the rehabilitation of a previously authorized project and only includes renovations, reconstruction and some additional similar types of protection works.
- b. The stream channel alignment or width is not being changed.
- c. New real estate takings or relocations of building or inhabitants are not required. The only real estate activities required are for the purposes of obtaining temporary easements for construction operations where applicable.
- d. Due to the previous low water quality rating of the river, and as most aquatic species do not inhabit the river, there should be no impacts on fish life from construction activities. Impacts on plant life will be those associated with vegetation removal from the banks as a result of construction or removal for flood control purposes. Revegetation measures will be carried out where it will not interfere with the intent of the flood control works. (Note: From all indications it is anticipated that the river

quality will gradually improve in the future as a result of this restoration project and the recent completion of two wastewater treatment plants in Fitchburg).

- e. Construction of the project will not have any ill effects of social, economic, or public health aspects.
- f. The rehabilitation work will enhance the project area from a visual and aesthetic viewpoint.
- g. The rehabilitation project does not present any new and/or controversial issues or items of work.
- h. The project is considered a minor action and that an Environmental Impact Statement is not required.

11.00 COORDINATION WITH OTHER AGENCIES

Coordination has been maintained throughout the course of the planning of this work with Federal, State and local agencies which have responsibilities or interests in the project.

12.00 CONCLUSIONS

Upon evaluating the information presented in this Environmental Assessment Report, it is my belief that construction of the proposed Channel Rehabilitation for local flood protection in the North Nashua River in Fitchburg, Massachusetts as indicated is in the best public interest.

Such rehabilitative work will not markedly change the hydraulic character of the channel but is required to insure the overall integrity of the channel. Under present deteriorated conditions, it is considered that structural failures would occur at localized areas during flood events of less than design magnitudes. The rehabilitation effort is a restoration of previously authorized and constructed facilities for flood protection purposes. The project may cause minimal temporary inconveniences during the work period only. It is determined that adverse short-term environmental impacts will be minimal and there will be no long-term adverse environmental impacts caused by the project.

In my evaluation, this assessment has been prepared in accordance with the National Environmental Policy Act of 1969 and will be coordinated with appropriate regulatory agencies. From all indications and the type of rehabilitation and restoration work involved, the local protection project is considered a minor action and can be accomplished

with subsequent minimization of environmental impacts. The assessment therefore precludes the need for preparation of a formal Environmental Impact Statement.

7 November 1977
(Date)


JOHN P. CHANDLER
Colonel, Corps of Engineers
Division Engineer

ATTACHMENT NO. 1

FITCHBURG LOCAL PROTECTION PROJECT
NORTH NASHUA RIVER

PRELIMINARY ABRIDGED SCOPE OF WORK

The preliminary abridged Scope of Work description is developed at the upstream limits of the work in the vicinity of the now-removed Cowee's Mill Dam, and proceeding downstream to the Leominster town line below the Fitchburg airport. Bank identification is made looking downstream.

Scope of Work

The following restorations are proposed:

a. Starting about 700 feet above Oak Hill Street bridge, re-stabilize right bank for about 200 feet and remove random boulders in same region along right bank.

b. Loose stone wall on left bank located about 300 feet upstream of Oak Hill Road bridge to be replaced with similar wall for length of approximately 60 feet. Wash-out of earth adjacent to Routes 12 and 31 to be filled with earth to match existing wall grade surrounding. Estimated fill 65 cubic yards to be placed against new section. Remove portions of breached wall lying in river.

c. At Daniels Street bridge re-grout cut stone wall upstream on right bank for a distance of about 100 feet.

d. Remove a few broken stone boulders immediately downstream of the bridge at left side. Restabilize right downstream bank immediately adjacent to the bridge abutment. Also, install approximately

12 feet of 18" RCP for extending storm sewer at bridge. Four shoaling areas, totalling approximately 800 ft., to be removed.

e. Repair channel bottom by grouting cut stones for an area of approximately 30 square yards between Kimball Street Bridge and the Boston and Maine Railroad bridge.

f. At River Street Bridge, Route 31, in the vicinity of West Street, remove from both banks dumped granite riprap covering about 125 feet each side. Remove old deteriorated concrete cribbing beneath the dumped granite (Crib Sites 1 and 2). Replace with poured concrete retaining walls and backfill to match surrounding grade. Construct concrete ramp on the right bank. Approximately 600 ft. of shoaling to be removed downstream of this site.

g. At Sheldon Street Bridge, repair right downstream concrete wall next to bridge.

h. East of Nockege Street immediately downstream of the foot bridge, remove or reposition remains of breached cut stone dam, approximately 80 pieces in 500 - 1000 pound sizes. Replacement with well graded rip-rap. Approximately 400 ft. of shoaling to be removed.

i. At River Street Bridge at West Street, Route 31, remove approximately 30 pieces large stone immediately downstream of the bridge. Do not disturb existing 12-inch crossing main in streambed. Approximately 400 ft. of shoaling to be removed upstream of this site.

j. At Circle Street Bridge, on the left bank downstream, remove dumped granite riprap and deteriorated concrete cribbing. Remove about 200 cubic yards of landslide fill in the streambed. Replace deteriorated cribbing (Crib Site No. 3) with concrete wall or uniform emplaced stone. Approximately 350 ft. of shoaling to be removed.

k. Along the right bank replace footing blocks in granite wall and re-grout.

l. Downstream of Rollstone Street Bridges, repair eroded grouted riprap on the left bank, about 150 feet in length.

m. About 500 feet upstream of Putnam Street on the right bank, repair existing concrete cribbing (Crib No. 4) by addition of concrete cap and refacing of several eroded stretcher members in a total length of about 150 feet. Remove approximately 450 ft. shoaling.

n. Construct 325 feet of concrete capping on top of existing wall. Remove approximately 300 ft. shoaling.

o. At Laurel Street along the right bank above the streambed and adjacent to railroad siding, remove about 250 feet of deteriorated concrete cribbing (Crib Site Nos. 5 and 6) and replace with concrete wall, three sections.

p. At Water Street Bridge, Route 12, vicinity of Walnut Street, upstream of Water Street on the left bank, restore approximately 300 feet of stone wall, removing temporary sand dike, plus material along base of wall in the streambed. Paint 300 feet of existing chainlink fence on top of wall and sandblast wall 310' long - 13' high. Remove approximately 400 ft. shoaling.

q. Prior to completion of Item p above, face existing concrete cribbing, (Crib Site No. 7), with a 1.5 ft. thick concrete veneer for a length of 250 feet, along right bank upstream of Water Street Bridge. Temporary access must be constructed in streambed to accomplish.

r. Deleted.

s. At the Power Station Dam, reset excess broken stone boulders downstream of the service dam. (Approximately 50 pieces 500 - 1000 pound range.)

t. Immediately upstream of the Harvard Street overpass, remove two midstream abutments from prior removed footbridge. Abutment in left bank to be retained but upper two courses of granite block to be regROUTed for safety.

u. Reset large broken stones in stream immediately downstream from Bemis Road dam.

v. Restore and prevent further erosion of banks and river bottom, regrade and place rip-rap protection on the adjacent river bank area and restore the outlet of the canal into the canal.

w. Remove shoaling.

x. In regard to vegetation and its management along the river, and keeping in mind the functional purpose of the project for flood protection and not allowing interferences with normal and possible flood flows, project vegetation maintenance guidelines were suggested.

(1) Clearing of lower limits of the channel from its bottom to elevation eight feet will consist of removal of all trees three

inches or more in diameter. At present, there are numerous small woody shoots in this zone and very few trees of significant size. This will set a base condition which will be maintained by local interest after completion of the Federal restoration project. This base condition, which will allow no greater than 3 inches in diameter, is intended to maintain the hydraulic character of the river channel so as not to overly inhibit flows during times of flood. It will also insure that no large trees will grow that could eventually uproot during flood stages causing blockage of the channel particularly at restrictive bridge openings causing the possible backwater flooding into developed areas in Fitchburg. A second zone between elevation eight and elevation 15 above river channel or to top of bank has been established wherein trees which lean out over the channel or are in stages of poor health having the inherent potential of falling in during extreme high flows will be removed. The amount of trees in this area held are limited to a small number.

Suggested vegetation management guidelines for the river will be carried out in station 580+00 through 440+00, and also 400+00 to Falulah Road. (See attached plates 1-4)



7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
559
560
561
562
563
564
565
566
567
568
569
569
570
571
572
573
574
575
576
577
578
579
579
580
581
582
583
584
585
586
587
588
589
589
590
591
592
593
594
595
596
597
598
599
599
600
601
602
603
604
605
606
607
608
609
609
610
611
612
613
614
615
616
617
618
619
619
620
621
622
623
624
625
626
627
628
629
629
630
631
632
633
634
635
636
637
638
639
639
640
641
642
643
644
645
646
647
648
649
649
650
651
652
653
654
655
656
657
658
659
659
660
661
662
663
664
665
666
667
668
669
669
670
671
672
673
674
675
676
677
678
679
679
680
681
682
683
684
685
686
687
688
689
689
690
691
692
693
694
695
696
697
698
699
699
700
701
702
703
704
705
706
707
708
709
709
710
711
712
713
714
715
716
717
718
719
719
720
721
722
723
724
725
726
727
728
729
729
730
731
732
733
734
735
736
737
738
739
739
740
741
742
743
744
745
746
747
748
749
749
750
751
752
753
754
755
756
757
758
759
759
760
761
762
763
764
765
766
767
768
769
769
770
771
772
773
774
775
776
777
778
779
779
780
781
782
783
784
785
786
787
788
789
789
790
791
792
793
794
795
796
797
798
799
799
800
801
802
803
804
805
806
807
808
809
809
810
811
812
813
814
815
816
817
818
819
819
820
821
822
823
824
825
826
827
828
829
829
830
831
832
833
834
835
836
837
838
839
839
840
841
842
843
844
845
846
847
848
849
849
850
851
852
853
854
855
856
857
858
859
859
860
861
862
863
864
865
866
867
868
869
869
870
871
872
873
874
875
876
877
878
879
879
880
881
882
883
884
885
886
887
888
889
889
890
891
892
893
894
895
896
897
898
899
900
901
902
903
904
905
906
907
908
909
909
910
911
912
913
914
915
916
917
918
919
919
920
921
922
923
924
925
926
927
928
929
929
930
931
932
933
934
935
936
937
938
939
939
940
941
942
943
944
945
946
947
948
949
949
950
951
952
953
954
955
956
957
958
959
959
960
961
962
963
964
965
966
967
968
969
969
970
971
972
973
974
975
976
977
978
979
979
980
981
982
983
984
985
986
987
988
989
989
990
991
992
993
994
995
996
997
998
999
1000
1001
1002
1003
1004
1005
1006
1007
1008
1009
10010
10011
10012
10013
10014
10015
10016
10017
10018
10019
10020
10021
10022
10023
10024
10025
10026
10027
10028
10029
10030
10031
10032
10033
10034
10035
10036
10037
10038
10039
10040
10041
10042
10043
10044
10045
10046
10047
10048
10049
10050
10051
10052
10053
10054
10055
10056
10057
10058
10059
10060
10061
10062
10063
10064
10065
10066
10067
10068
10069
10070
10071
10072
10073
10074
10075
10076
10077
10078
10079
10080
10081
10082
10083
10084
10085
10086
10087
10088
10089
10090
10091
10092
10093
10094
10095
10096
10097
10098
10099
100100
100101
100102
100103
100104
100105
100106
100107
100108
100109
100110
100111
100112
100113
100114
100115
100116
100117
100118
100119
100120
100121
100122
100123
100124
100125
100126
100127
100128
100129
100130
100131
100132
100133
100134
100135
100136
100137
100138
100139
100140
100141
100142
100143
100144
100145
100146
100147
100148
100149
100150
100151
100152
100153
100154
100155
100156
100157
100158
100159
100160
100161
100162
100163
100164
100165
100166
100167
100168
100169
100170
100171
100172
100173
100174
100175
100176
100177
100178
100179
100180
100181
100182
100183
100184
100185
100186
100187
100188
100189
100190
100191
100192
100193
100194
100195
100196
100197
100198
100199
100200
100201
100202
100203
100204
100205
100206
100207
100208
100209
100210
100211
100212
100213
100214
100215
100216
100217
100218
100219
100220
100221
100222
100223
100224
100225
100226
100227
100228
100229
100230
100231
100232
100233
100234
100235
100236
100237
100238
100239
100240
100241
100242
100243
100244
100245
100246
100247
100248
100249
100250
100251
100252
100253
100254
100255
100256
100257
100258
100259
100260
100261
100262
100263
100264
100265
100266
100267
100268
100269
100270
100271
100272
100273
100274
100275
100276
100277
100278
100279
100280
100281
100282
100283
100284
100285
100286
100287
100288
100289
100290
100291
100292
100293
100294
100295
100296
100297
100298
100299
100300
100301
100302
100303
100304
100305
100306
100307
100308
100309
100310
100311
100312
100313
100314
100315
100316
100317
100318
100319
100320
100321
100322
100323
100324
100325
100326
100327
100328
100329
100330
100331
100332
100333
100334
100335
100336
100337
100338
100339
100340
100341
100342
100343
100344
100345
100346
100347
100348
100349
100350
100351
100352
100353
100354
100355
100356
100357
100358
100359
100360
100361
100362
100363
100364
100365
100366
100367
100368
100369
100370
100371
100372
100373
100374
100375
100376
100377
100378
100379
100380
100381
100382
100383
100384
100385
100386
100387
100388
100389
100390
100391
100392
100393
100394
100395
100396
100397
100398
100399
100400
100401
100402
100403
100404
100405
100406
100407
100408
100409
100410
100411
100412
100413
100414
100415
100416
100417
100418
100419
100420
100421
100422
100423
100424
100425
100426
100427
100428
100429
100430
100431
100432
100433
100434
100435
100436
100437
100438
100439
100440
100441
100442
100443
100444
100445
100446
100447
100448
100449
100450
100451
100452
100453
100454
100455
100456
100457
100458
100459
100460
100461
100462
100463
100464
100465
100466
100467
100468
100469
100470
100471
100472
100473
100474
100475
100476
100477
100478
100479
100480
100481
100482
100483
100484
100485
100486
100487
100488
100489
100490
100491
100492
100493
100494
100495
100496
100497
100498
100499
100500
100501
100502
100503
100504
100505
100506
100507
100508
100509
100510
100511
100512
100513
100514
100515
100516
100517
100518
100519
100520
100521
100522
100523
100524
100525
100526
100527
100528
100529
100530
100531
100532
100533
100534
100535
100536
100537
100538
100539
100540
100541
100542
100543
100544
100545
100546
100547
100548
100549
100550
100551
100552
100553
100554
100555
100556
100557
100558
100559
100560
100561
100562
100563
100564
100565
100566
100567
100568
100569
100570
100571
100572
100573
100574
100575
100576
100577
100578
100579
100580
100581
100582
100583
100584
100585
100586
100587
100588
100589
100589
100590
100591
100592
100593
100594
100595
100596
100597
100598
100599
100599
100600
100601
100602
100603
100604
100605
100606
100607
100608
100609
100610
100611
100612
100613
100614
100615
100616
100617
100618
100619
100620
100621
100622
100623
100624
100625
100626
100627
100628
100629
100630
100631
100632
100633
100634
100635
100636
100637
100638
100639
100640
100641
100642
100643
100644
100645
100646
100647
100648
100649
100650
100651
100652
100653
100654
100655
100656
100657
100658
100659
100660
100661
100662
100663
100664
100665
100666
100667
100668
100669
100670
100671
100672
100673
100674
100675
100676
100677
100678
100679
100680
100681
100682
100683
100684
100685
100686
100687
100688
100689
100689
100690
100691
100692
100693
100694
100695
100696
100697
100698
100699
100699
100700
100701
100702
100703
100704
100705
100706
100707
100708
100709
100710
100711
100712
100713
100714
100715
100716
100717
100718
100719
100720
100721
100722
100723
100724
100725
100726
100727
100728
100729
100730
100731
100732
100733
100734
100735
100736
100737
100738
100739
10074

4

E

4

6

1

U S ARMY



18 to be removed.
In the year 1800; the st. bridge,
old red cap in river bottom and well graded for
brown street to prevent further encroaching

- stones or dry, wet with wet grouted rip-rap
- existing stones - existing stones removed
- reset large stones creating a uniform to irregular pattern
- add new stones - irregular stones - 8" to 12"

As only the existing dam is to be used to provide
bridge site 1, a new diversion site is to be
provided at site 2 to accommodate


Repair approximately 1000 ft. of 100 ft. wide
i Repair grouted rib-rope

On Repair-existing structures, including the addition of a concrete cap, and the repair of several structures after removal of the temporary structures.

GRAPHIC SCALES

LEGEND
— S S — SEISMIC SURVEY
● BORING LOG

PLATE I



۲۷۷

(d) the concrete wall on the left bank will be 10 m high in the elevations from left bank with Remove shoring.

⑥ From a short distance on the cobbling 1' below No. 5 and N.E. of a large granite boulder.

(P) ON THE EASTERN SIDE, APPROXIMATELY 40 FEET S. OF THE POINT WHERE THE CREEK MEETS THE RIVER.

wait; remove temporary seal like that in step of long time
- for the number of repeat units to be added to the
- previous unit of the long time period. The
- repeat unit is the same as the previous unit.

It is not necessary to prove that the same
border-line exists in France as in Ger-

6

F

6

11

U S ARMY

NASHUA

RIVER

243

G H B U R G

W-STEAM PUMPS 1000' x 2' x 1'
400' x 100' x 100' STEAM TUBE
400' x 100' x 100' STEAM TUBE
400' x 100' x 100' STEAM TUBE

GRAPHS 13.1.1

DEPARTMENT OF THE ARMY
NEW ENGLAND REGION
COMMITTEE ON DRAINS
WALTHAM, MASS

TER RESOURCES DEVELOPMENT PROJECT
FITCHBURG, MASSACHUSETTS

NORTH NASHUA RIVER
CHANNEL REHABILITATION
GENERAL PLAN NO 2

PLATE 2

MATCH LINE PLATE 2



KEY

- ④ Reset one broken stones in stream immediately down stream from Bemis Road dam.
- ⑤ Restore and prevent further erosion of banks and river bottom. Remove and place riprap protection on the adjacent river bank and restore the outlet of the canal into the river.
- ⑥ Remove shoaling.


6

0

6

B


U.S. ARMY



GRAPHIC SCALE

PLATE 3


U. S. ARMY



AT AREA (B)


TYPICAL SECTION AT CRIB SITE NO 1 AREA (F)

SCALE 1"=5'




TYPICAL SECTION AT CRIB SITE NO 2 AREA (F)

SCALE 1"=5'




TYPICAL SECTION AT AREA (M)

SCALE 1"=5'




TYPICAL SECTION AT AREA (O)

SCALE 1"=5'




TYPICAL SECTION AT AREA (O)

SCALE 1"=5'




TYPICAL SECTION AT AREA (V)

SCALE HOR 1"=10'
VERT 1"=5'

TYPICAL SECTION AT AREA (N)

SCALE 1/2"=1'-0"



TYPICAL SECTION AT AREA (Q)

SCALE 1"=5'



REVISION	DATE	DESCRIPTION	BY
DEPARTMENT OF THE ARMY NEW ENGLAND SECTION COAST & ENGINEERS WALTHAM, MASS.			
WATER RESOURCES DEVELOPMENT PROJECT FITCHBURG, MASSACHUSETTS			
NORTH NASHUA RIVER CHANNEL REHABILITATION TYPICAL SECTIONS			
NORTH NASHUA RIVER MASSACHUSETTS			
APPROVED			
CHIEF ENGINEER'S OFFICE			
SPEC. NO.			
DRAWING NUMBER			
MER-34			
SHEET			

PLATE 4

